Inspection logged	Works reference					Highway				Inspection
date	number	Road/Street	Area	Works location description	Promoter	authority	Works start date	Works end date	Inspection type	category
	N7152J027-153160-3-	EAST TILBURY		From outside property number 69 to the junction						Site
07/07/2023 10:25	WHP02	ROAD		with Northumberland Road	Limited	COUNCIL	26/07/2023 00:00	04/08/2023 00:00	Live site	occupancy
	N7152153160-5-WHP-	EAST TILBURY			Nexfibre Networks	THURROCK			Non compliance	Follow up
07/07/2023 10:05		ROAD	LINFORD	In the footway between property numbers 1-6	Limited	COUNCIL	26/06/2023 10:00	28/06/2023 10:10	•	completion
0.70.72020 20.00			2	Muckingford Road to be closed from the junction		00011012	20,00,2020 10.00	20,00,2020 10:10	ionow up	completion
•	N7152LINFORD-TRUNK-	MUCKINGFORD		with Beechcroft Avenue to the junction with Blue	Nexfibre Networks	THURROCK				Site
26/06/2023 13:57	WHP	ROAD	LINFORD	Anchor Road	Limited	COUNCIL	22/05/2023 08:00	23/06/2023 17:00	Live site	occupancy
•				Muckingford Road to be closed from the junction						
	N7152LINFORD-TRUNK-	MUCKINGFORD		with Beechcroft Avenue to the junction with Blue			/ /			
19/06/2023 17:11	. WHP	ROAD	LINFORD	Anchor Road Muckingford Road to be closed from the junction	Limited	COUNCIL	22/05/2023 08:00	23/06/2023 00:00	Live site	Conditions
	N7152LINFORD-TRUNK-	MUCKINGFORD		with Beechcroft Avenue to the junction with Blue	Nevfihre Networks	THURROCK				
19/06/2023 17:11		ROAD	LINFORD	Anchor Road	Limited	COUNCIL	22/05/2023 08:00	23/06/2023 00:00	Live site	Routine
15/00/2025 17:11	VVIII	NOAD	LINIOND	Muckingford Road to be closed from the junction	Limited	COONCIL	22/03/2023 00.00	23/00/2023 00:00	LIVE SILE	Routine
•	N7152LINFORD-TRUNK-	MUCKINGFORD		with Beechcroft Avenue to the junction with Blue	Nexfibre Networks	THURROCK				
24/05/2023 11:35	WHP	ROAD	LINFORD	Anchor Road	Limited	COUNCIL	22/05/2023 08:00	11/06/2023 00:00	Live site	Conditions
				Muckingford Road to be closed from the junction						
	N7152LINFORD-TRUNK-	MUCKINGFORD		with Beechcroft Avenue to the junction with Blue	Nexfibre Networks					
24/05/2023 11:35	WHP	ROAD	LINFORD	Anchor Road	Limited	COUNCIL	22/05/2023 08:00	11/06/2023 00:00	Live site	Category A
	N7152153160-5-WHP-	EAST TILBURY			Nexfibre Networks	THURROCK			Non compliance	Follow up
19/05/2023 12:26	LS	ROAD	LINFORD	In the footway between property numbers 1-6	Limited	COUNCIL	09/05/2023 10:00	11/05/2023 14:00	follow up	completion
					UK POWER	TUUDDOCK				
10/04/2022 07:52	F620020F42F00	CONTEDEST DOAD		O/C 47 DIC IN E/M CC47 OD7	NETWORKS	THURROCK	12/04/2022 11:50	14/04/2022 11:15	Deimetetement	Davidia a
19/04/2023 07:52	EC30029513509	SOMERSET ROAD		O/S 47 DIG IN F/W SS17 OPZ	EASTERN & UK POWER	COUNCIL	12/04/2023 11:58	14/04/2023 11:15	Reinstatement	Routine
					NETWORKS	THURROCK				Site
19/04/2023 07:50	EC30029513509	SOMERSET ROAD		O/S 47 DIG IN F/W SS17 OPZ	EASTERN &	COUNCIL	12/04/2023 11:58	14/04/2023 11:15	Live site	occupancy
				,						
İ		BUCKINGHAM		BUCKINGHAM HILL ROAD, NEAR ENTRANCE OF		THURROCK				Site
14/04/2023 07:44	BC311WD5N547K001	HILL ROAD	THURROCK	RECYCLING CENTRE	ВТ	COUNCIL	12/04/2023 01:00	12/04/2023 01:00	Live site	occupancy
					UK POWER					
42/04/2022 42 52	FC30030F43F00	COMEDCET DOAD		O/C 47 DIC IN F/W CC47 CC7	NETWORKS	THURROCK	12/04/2022 44 52	10/04/2022 44 52	I in a site	Davidio -
13/04/2023 13:58	EC30029513509	SOMERSET ROAD		O/S 47 DIG IN F/W SS17 OPZ	EASTERN &	COUNCIL	12/04/2023 11:58	18/04/2023 11:58	Live site	Routine
	N7152153160-5-WHP-	EAST TILBURY			Nexfibre Networks	THURROCK			Non compliance	Joint site
06/04/2023 11:36	LS	ROAD	LINFORD	In the footway between property numbers 1-6	Limited	COUNCIL	21/02/2023 10:00	23/02/2023 15:00	follow up	visit

05/04/2023 08:05	FN014M78181	EAST TILBURY ROAD	LINFORD	91	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	28/03/2023 11:12	05/04/2023 00:00	Live site	Site occupancy
30/03/2023 09:50		EAST TILBURY ROAD	LINFORD		ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	28/03/2023 00:00	03/04/2023 00:00		Conditions
28/03/2023 12:58	EN014M78181	EAST TILBURY ROAD	LINFORD	91	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	28/03/2023 00:00	03/04/2023 00:00	Live site	Routine
24/03/2023 09:28	D2006-NETOM-	LINFORD ROAD		Traffic Head Light on Linford Road	Netomnia Limited	THURROCK COUNCIL	22/03/2023 09:04	23/03/2023 16:31		Site occupancy
23/03/2023 13:35	D2006-NETOM- GNSPUR443-TM	LINFORD ROAD		Traffic Head Light on Linford Road	Netomnia Limited	THURROCK COUNCIL	22/03/2023 09:04	23/03/2023 17:00	Live site	Category A
23/03/2023 12:11	JT70089219160	BUCKINGHAM HILL ROAD		Buckingham Hill Road junction with Stanford Road - Swarco are required to carry out loop cutting at Signal Junction	THURROCK COUNCIL	THURROCK COUNCIL	16/03/2023 19:30	16/03/2023 23:59	Live site	Site occupancy
13/03/2023 08:17	EN014M76957	EAST TILBURY ROAD	LINFORD	6	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	07/03/2023 00:00	11/03/2023 16:21	Reinstatement	Category B
13/03/2023 07:59	EN014M76957	EAST TILBURY ROAD	LINFORD	6	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	07/03/2023 00:00	11/03/2023 16:21	Live site	Site occupancy
09/03/2023 12:22	N7152153160-3-WHP- LS01	SOMERSET ROAD	LINFORD	From the side of 29 Northumberland Road to outside 26 Somerset Road	Nexfibre Networks Limited	THURROCK COUNCIL	23/02/2023 10:30	08/03/2023 16:50	Live site	Site occupancy
08/03/2023 12:51	N7152153160-3-WHP-	SOMERSET ROAD	LINFORD	From the side of 29 Northumberland Road to outside 26 Somerset Road	Nexfibre Networks	THURROCK COUNCIL	23/02/2023 10:30	08/03/2023 00:00	Live site	Routine
00/03/2023 12:31	2001	SOMENSET NOAD	EINI OND	outside 20 some set nodu	Limited	COONCIL	25/02/2023 10:30	00/03/2023 00:00	LIVE SICE	Noutine
	N7152153160-3-WHP-			From the side of 29 Northumberland Road to	Nexfibre Networks	THURROCK				
07/03/2023 14:33		SOMERSET ROAD	LINFORD	outside 26 Somerset Road	Limited	COUNCIL	23/02/2023 10:30	08/03/2023 00:00	Live site	Category A
07/03/2023 13:03	N7152NBU150686-2- WHP-LS	MUCKINGFORD ROAD	LINFORD	AT THE JUNCTION WITH EAST TILBURY ROAD	Nexfibre Networks Limited	THURROCK COUNCIL	07/03/2023 10:20	10/03/2023 00:00	Live site	Category A

		I	1							Τ
07/03/2023 10:57	N7152153160-5-WHP-	EAST TILBURY ROAD	LINFORD	In the footway between property numbers 1-6	Nexfibre Networks Limited	THURROCK COUNCIL	21/02/2023 10:00	23/02/2023 15:00	Poinstatement	Category B
07/03/2023 10.37	1.5	ROAD	LINFORD	in the rootway between property numbers 1-0	Limited	COONCIL	21/02/2023 10:00	23/02/2023 13.00	Reinstatement	Category B
07/02/2022 40 42	ENIO4 48 47 COE 7	EAST TILBURY	LINEODD		ESSEX AND	THURROCK	07/02/2022 00 00	42/02/2022 00 00	11.	David a
07/03/2023 10:43	EN014M76957	ROAD	LINFORD	6	SUFFOLK WATER	COUNCIL	07/03/2023 00:00	13/03/2023 00:00	Live site	Routine
	N7152153160-3-WHP-			From the side of 29 Northumberland Road to	Nexfibre Networks	THURROCK				
24/02/2023 14:57	LS01	SOMERSET ROAD	LINFORD	outside 26 Somerset Road	Limited	COUNCIL	23/02/2023 10:30	08/03/2023 00:00	Live site	Routine
			CHADWELL		ESSEX AND	THURROCK				
22/02/2023 13:56	EN014M76021	LINFORD ROAD	ST MARY	O/s and Opp St Marys Church	SUFFOLK WATER	COUNCIL	15/02/2023 00:00	21/02/2023 18:00	Live site	Routine
			CHADWELL		ESSEX AND	THURROCK				Site
22/02/2023 13:53	EN014M76021	LINFORD ROAD	ST MARY	O/s and Opp St Marys Church	SUFFOLK WATER	COUNCIL	15/02/2023 00:00	21/02/2023 18:00	Live site	occupancy
			CHADWELL		ESSEX AND	THURROCK				
21/02/2023 14:49	EN014M76021	LINFORD ROAD		O/s and Opp St Marys Church	SUFFOLK WATER	COUNCIL	15/02/2023 00:00	28/02/2023 00:00	Live site	Third party
			CHADWELL		ESSEX AND	THURROCK				
20/02/2023 14:34	EN014M76021	LINFORD ROAD	ST MARY	O/s and Opp St Marys Church	SUFFOLK WATER	COUNCIL	15/02/2023 00:00	28/02/2023 00:00	Live site	Third party
		EACT TH BLIDV				THURROCK				Cito
20/02/2023 12:23	BC007WDPF489Z	EAST TILBURY ROAD		FOOTWAY OUTSIDE NO 101	ВТ	THURROCK COUNCIL	14/02/2023 13:34	17/02/2023 13:47	Live site	Site occupancy
			CHADIMELL		ECCEV AND	THURBOOK				
15/02/2023 14:42	EN014M76021	LINFORD ROAD	CHADWELL ST MARY	O/s and Opp St Marys Church	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	15/02/2023 00:00	28/02/2023 00:00	Live site	Routine
-,-,-				27.2.2.2.7			.,.,	-,-,-		
				Emergency Pothole Repairs						
				Road Closure from Beachcroft to Blue Anchor Checked one network, can see Virgin Media is						
		MUCKINGFORD		working along Muckingford but they are able to	THURROCK	THURROCK				Site
09/02/2023 13:02	JT60080750276	ROAD		work within our closure.	COUNCIL	COUNCIL	08/02/2023 09:00	08/02/2023 15:00	Live site	occupancy
	N7152LINT13-WHP-	MUCKINGFORD		Opposite property number 10 Muckingford Road	Nexfibre Networks	THURROCK				
09/02/2023 13:00	LS01	ROAD	LINFORD	to just past the junction with Beechcroft Avenue	Limited	COUNCIL	08/02/2023 10:00	10/02/2023 00:00	Live site	Routine
	NK152NBU150686WHP	MUCKINGFORD				THURROCK				Site
06/02/2023 09:03		ROAD	LINFORD	18m from the junction with East Tilbury Road	VIRGIN MEDIA	COUNCIL	23/01/2023 11:45	03/02/2023 14:45	Live site	occupancy

						THURROCK				Site
01/02/2023 08:51	BC007WDPFLF8L	SOMERSET ROAD		FOOTWAY OUTSIDE OF NO 65	BT	COUNCIL	27/01/2023 00:00	31/01/2023 00:00	Live site	occupancy
						THURROCK				Site
27/01/2023 14:27	BC007WDNW0W7K	SOMERSET ROAD		FOOTWAY OUTSIDE OF NO 57	ВТ	COUNCIL	24/01/2023 00:00	26/01/2023 00:00	Live site	occupancy
	NK152NBU150686WHP	MUCKINGFORD				THURROCK				
24/01/2023 08:12		ROAD	LINFORD	18m from the junction with East Tilbury Road	VIRGIN MEDIA	COUNCIL	23/01/2023 11:45	05/02/2023 00:00	Live site	Category A
, , , , , , , , , , , , , , , , , , , ,	_						-,-,-	,.,		
06/04/202242	NK152VM991017WHP_			From Outside Council Office to Opposite The	VIDCINI NAEDIA	THURROCK	06/04/2022 00 55	00/04/2022 00 00	11	Site
06/01/2023 12:24	BK01	LINFORD ROAD	ST MARY	Laurels in footway.	VIRGIN MEDIA	COUNCIL	06/01/2023 08:55	09/01/2023 00:00	Live site	occupancy
	BC411SAWD0HWJ4G00			SIDE OF 1 ALURIC CLOSE, ON VERGE AREA OF		THURROCK				Site
29/12/2022 08:00	1	LINFORD ROAD	THURROCK	LINFORD ROAD RM16	ВТ	COUNCIL	20/12/2022 16:40	21/12/2022 16:40	Live site	occupancy
			CHADWELL	Junction of Brentwood Road to Entrance of		THURROCK				Site
19/12/2022 14:10	NK152LINT9WHP BK01	LINFORD ROAD	ST MARY	Atherton Gardens in footway.	VIRGIN MEDIA	COUNCIL	14/12/2022 15:00	16/12/2022 16:35	Live site	occupancy
22/11/2022 11:14	DC311WDENE47V001	BUCKINGHAM HILL ROAD	TUUDDOCK	BUCKINGHAM HILL ROAD, NEAR ENTRANCE OF	DT	THURROCK COUNCIL	22/05/2022 01:00	24/05/2022 01:00	Non compliance	Joint site visit
22/11/2022 11:14	BC311WD5N547K001	HILL ROAD	THURROCK	RECYCLING CENTRE	BT	COUNCIL	23/05/2022 01:00	24/05/2022 01:00	Tollow up	VISIL
		BUCKINGHAM		BUCKINGHAM HILL ROAD, NEAR ENTRANCE OF		THURROCK				
01/11/2022 07:36	BC311WD5N547K001	HILL ROAD	THURROCK	RECYCLING CENTRE	ВТ	COUNCIL	23/05/2022 01:00	24/05/2022 01:00	Reinstatement	Routine
		DUCKINGUANA		NEAD AAAW AND BUCKINGHAAA HIIL BOAD		THURDOOK				6.1
25/10/2022 08:05	BC008PTMS475119	BUCKINGHAM HILL ROAD		NEAR MAYLAND BUCKINGHAM HILL ROAD STANFORD LE HOPE SS17 OPP	ВТ	THURROCK COUNCIL	23/10/2022 10:00	23/10/2022 15:00	Live site	Site occupancy
23/10/2022 00:03	DC0001 11V15475115	THEE ROAD		STANTOND LETTON E 3317 OF T	51	COONCIL	23/10/2022 10:00	25/10/2022 15:00	LIVE SILE	оссиринсу
	D2006-NETOM-			Build Verge Chamber OPP The Parish Church of		THURROCK				
12/10/2022 12:30	GNSPUR106	LINFORD ROAD		Chadwell Saint Mary, Grays	Netomnia Limited	COUNCIL	12/10/2022 10:00	14/10/2022 15:00	Live site	Category A
			CHADWELL			THURROCK				Site
05/10/2022 14:07	AD02660693112_TL2	LINFORD ROAD	ST MARY	junction with Chadwell Hill	ANGLIAN WATER	COUNCIL	03/10/2022 11:32	03/10/2022 14:00	Live site	occupancy
						THURDOON				Cita
06/09/2022 10:38	BC007WDHNN06W	SOMERSET ROAD		FOOTWAY OUTSIDE OF NO 47	ВТ	THURROCK COUNCIL	05/09/2022 08:53	05/09/2022 12:05	Live site	Site occupancy
00/03/2022 10.30	DCCCO VVDI IIVIVOOVV	SOMENSET NOAD		I COT WAT COTSIDE OF NO 47	ויין	COUNCIL	03/03/2022 00.55	03/03/2022 12:03	FIAC 211C	occupancy

	AD037R059746943_2_T		CHADWELL			THURROCK				Site
31/08/2022 13:13	L3	LINFORD ROAD	ST MARY	junction with Brentwood Road	ANGLIAN WATER	COUNCIL	12/05/2022 00:00	12/05/2022 23:00	Live site	occupancy
						THURROCK				
15/06/2022 15:14	BC311WD2PML6J002	SOMERSET ROAD	THURROCK	O/S 64 to O/S 36 Somerset Road	BT	COUNCIL	06/06/2022 09:30	07/06/2022 17:00	Reinstatement	Third party
16/02/2022 15:03	JT60079742810	EAST TILBURY ROAD		Emergency works - Dangerous Man hole cover C/Way incursion - men on site now Multiway Temp Traffic Lights Buckingham hill Road Junction with Walton Hall road, Northumberland Road & East Tilbury Road	THURROCK COUNCIL	THURROCK COUNCIL	13/02/2022 13:00	15/02/2022 14:00	Live site	Site occupancy
28/01/2022 15:41	BC00828JANWD2V3L5H	MUCKINGFORD ROAD		JCR 12 Muckingford road/ Beechcroft avenue	вт	THURROCK COUNCIL	28/01/2022 00:00	28/01/2022 13:08	Live site	Site occupancy
18/01/2022 16:42	EN013214104	SOMERSET ROAD	LINFORD	o/s 29 to o/s 30 (full road crossing)	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	22/07/2021 09:17	29/07/2021 13:20	Reinstatement	Category B
11/11/2021 11:36	EN014M26602	WALTONS HALL ROAD	LINFORD	Junction of Mucking Wharf Road & Butts Lane	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	11/11/2021 09:42	16/11/2021 00:00	Live site	Conditions
11/11/2021 11:36	EN014M26602	WALTONS HALL ROAD	LINFORD	Junction of Mucking Wharf Road & Butts Lane	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	11/11/2021 09:42	16/11/2021 00:00	Live site	Routine
28/10/2021 16:06	JT400HT0121-21	LINFORD ROAD		From J/W Waterson Road to J/W Sandy Lane Roundabout	THURROCK COUNCIL	THURROCK COUNCIL	28/10/2021 12:15	28/10/2021 15:55	Live site	Site occupancy
25/10/2021 18:26	EN014M40525	SOMERSET ROAD	LINFORD	19b	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	20/10/2021 13:38	25/10/2021 13:33	Live site	Site occupancy
27/07/2021 11:53	EN013214104	SOMERSET ROAD	LINFORD	o/s 29 to o/s 30 (full road crossing)	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	22/07/2021 09:17	28/07/2021 00:00	Live site	Conditions
27/07/2021 11:52	EN013214104	SOMERSET ROAD	LINFORD	o/s 29 to o/s 30 (full road crossing)	ESSEX AND SUFFOLK WATER	THURROCK COUNCIL	22/07/2021 09:17	28/07/2021 00:00	Live site	Routine
01/07/2021 21:02	AZ0071000850526	EAST TILBURY ROAD		Outside 105 EAST TILBURY ROAD in the footway	CADENT GAS LIMITED	THURROCK COUNCIL			Reinstatement	Routine

						Has the				
						promoter		Call		
	Inspection	Inspection reference		Outcome		been	Call	reference		Fixed on
Inspection date	start time	number	Inspection outcome	details	Failure reasons	contacted?		number	Call summary	site
inspection date	Start time	number	inspection outcome	uetalis	rallule leasons	contacteur	COIILact	Hullibei	Call Sulfilliary	Site
		N7152J027-153160-3-				Not				
07/07/2022 10:20	10.20		Marks in progress							
07/07/2023 10:20	10.20	WHP02-INSP-01	Works in progress			provided		+		+
		N7152153160-5-WHP-				Not				
07/07/2022 10:02	10.02	LS-INSP-04	Passed			provided				
07/07/2023 10:02	10.02	L3-1113F-04	rasseu			provided		 		+
		N7152LINFORD-TRUNK-				Not				
26/06/2022 12:55	12.55	WHP-INSP-05				provided				
26/06/2023 13:55	13:55	WHP-1113P-05	Works stopped			provided		+		+
		N7152LINFORD-TRUNK-				Not				
19/06/2023 14:00	14:00					provided				
19/00/2023 14.00	14.00	WHP-11N3P-04	Passed			provided				+
		N7152LINFORD-TRUNK-				Not				
19/06/2023 14:00	14.00		Passed			provided				
19/00/2023 14.00	14.00	WITE-1113F-03	rasseu			provided				+
		N7152LINFORD-TRUNK-				Not				
24/05/2023 11:32	11.22		Passed			provided				
24/03/2023 11.32	11.52	WHP-11N3P-02	rasseu			provided		+		+
		N7152LINFORD-TRUNK-				Not				
24/05/2023 11:32	11.22	WHP-INSP-01	Passed			provided				
24/03/2023 11.32	11.52	WITE-INSE-OI	rasseu			provided				
		N7152153160-5-WHP-			Acute angles,	Not				
19/05/2023 12:21	12:21	LS-INSP-03	Failed - low		Proximity	provided				
					,	Ť		1		
		EC30029513509-INSP-				Not				
19/04/2023 07:50	07:50	03	Passed			provided				
						İ				
		EC30029513509-INSP-				Not				
19/04/2023 07:50	07:50	02	Works stopped			provided				
			• •							
		BC311WD5N547K001-				Not				
14/04/2023 07:43	07:43	INSP-03	Works stopped			provided				
			• •							
		EC30029513509-INSP-				Not				
13/04/2023 13:56	13:56	01	Passed			provided				
		N7152153160-5-WHP-	Further inspections			Not				
06/04/2023 11:00	11:00	LS-INSP-02	required	<u> </u>		provided				

		EN014M78181-INSP-			Not				
05/04/2023 07:37	07:37		Works stopped		provided				
30/03/2023 09:40	09:40	EN014M78181-INSP- 02	Passed		Not provided				
28/03/2023 12:50	12:50	EN014M78181-INSP- 01 D2006-NETOM-	Passed		Not provided				
24/03/2023 09:26	09:26	GNSPUR443-TM-INSP-	Works stopped		Not provided				
23/03/2023 13:31	13:31	GNSPUR443-TM-INSP-	Passed		Not provided				
23/03/2023 12:01	12:01	JT70089219160-INSP- 01	Works stopped		Not provided				
13/03/2023 07:57	07:57	EN014M76957-INSP- 03	Passed		Not provided				
13/03/2023 07:57	07:57	EN014M76957-INSP- 02	Works stopped		Not provided				
09/03/2023 12:21	12:21	N7152153160-3-WHP- LS01-INSP-04	Works stopped		Not provided				
08/03/2023 12:35	12:35	N7152153160-3-WHP- LS01-INSP-03	Failed - low	Signage, Barriers	Not provided				
07/03/2023 14:01	14:01	N7152153160-3-WHP- LS01-INSP-02	Failed - high	Signage, Traffic control, Pedestrian provision, Equipment	Yes	Laura	VM/CIP/44 3242	High risk SLG logged via phone call to Virgin Media Street Works department at 14:25pm.	No
07/03/2023 13:01		N7152NBU150686-2-	Passed		Not provided			·	

N7152153160-5-WHP Falled - low	1				l		1	I	l	1
07/03/2023 10:32 10:32 15-INSP-01 Falled -low Proximity Provided										
07/03/2023 10:32 10:32 15-INSP-01 Failed - low Proximity provided										
07/03/2023 10:32 10:32 15-INSP-01 Failed - low Proximity provided										
07/03/2023 10:32 10:32 S-INSP-01 Failed - low Proximity Provided										
EN014M76957-INSP- 24/02/2023 14:44 14:44 1501-INSP- 22/02/2023 13:54 13:54 13:54 05 EN014M76021-INSP- 22/02/2023 13:50 13:50 EN014M76021-INSP- 22/02/2023 14:41 14:41 14:43 EN014M76021-INSP- 22/02/2023 14:41 EN014M76021-INSP- 21/02/2023 14:41 EN014M76021-INSP- 21/02/2023 14:41 EN014M76021-INSP- 20/02/2023 14:15 EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- 20/02/2023 14:15 EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- D0/02/2023 14:15 EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- D0/02/2023 14:30 EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M76021-INSP- EN014M760			N7152153160-5-WHP-			Acute angles,	Not			
07/03/2023 10:27 10:27 01	07/03/2023 10:32	10:32	LS-INSP-01	Failed - low		Proximity	provided			
07/03/2023 10:27 10:27 01			EN014M76957-INSP-				Not			
24/02/2023 14:44	07/03/2023 10:27			Passed						
24/02/2023 14:44										
24/02/2023 14:44			N7452452460 2 WULD							
EN014M76021-INSP- Passed	24/02/2023 14:44	14:44		Failed - low		Signage				
22/02/2023 13:54 13:54 05	,,					- 0 - 0-				
EN014M76021-INSP- Works stopped	22/02/2022 12.54			Dassad						
22/02/2023 13:50	22/02/2023 13:54	13:54	05	Passeu			provided			
EN014M76021-INSP- 20/02/2023 14:41										
21/02/2023 14:41	22/02/2023 13:50	13:50	04	Works stopped			provided			
EN014M76021-INSP- Failed - low Signage, Traffic control provided			EN014M76021-INSP-				Not			
20/02/2023 14:15	21/02/2023 14:41	14:41	03	Passed			provided			
20/02/2023 14:15			EN014M76021-INSP-				Not			
20/02/2023 12:14 12:14 01 Works stopped provided Not Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not Not Not Not Not Not Not Not Not Not	20/02/2023 14:15	14:15		Failed - low		Signage, Traffic control				
20/02/2023 12:14 12:14 01 Works stopped provided Not Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not provided Not Not Not Not Not Not Not Not Not Not			RC007WDDE4897_INSD_				Not			
15/02/2023 14:30	20/02/2023 12:14			Works stopped						
15/02/2023 14:30										
09/02/2023 13:00	15/02/2023 14:30			Passed						
09/02/2023 13:00	13/02/2023 11.30	11.50	01	1 43364			provided			
09/02/2023 13:00										
09/02/2023 13:00										
09/02/2023 13:00			JT60080750276-INSP-				Not			
09/02/2023 12:57	09/02/2023 13:00	13:00		Works stopped						
09/02/2023 12:57										
09/02/2023 12:57			N7152HNT13-WHD-				Not			
NK152NBU150686WH Not	09/02/2023 12:57	12:57		Passed						
	06/02/2023 09:00	09·00		Works stopped			Not provided			

01/02/2022 00:40	00.40	BC007WDPFLF8L-INSP-	M/a dia akao a a		Not		
01/02/2023 08:49	08:49	01	Works stopped		provided		
/- / /		BC007WDNW0W7K-			Not		
27/01/2023 14:25	14:25	INSP-01	Works stopped		provided		
		NK152NBU150686WH	_		Not		
24/01/2023 08:00	08:00	P_BK01-INSP-01	Passed		provided		
		NK152VM991017WHP			Not		
06/01/2023 12:22	12:22	_BK01-INSP-01	Works stopped		provided		
		BC411SAWD0HWJ4G0			Not		
29/12/2022 07:58	07:58	01-INSP-01	Works stopped		provided		
		NK152LINT9WHP_BK0			Not		
19/12/2022 14:09	14:09	1-INSP-01	Works stopped		provided		
22/11/2022 11:00	11:00	BC311WD5N547K001- INSP-02	Further inspections required		Not provided		
		BC311WD5N547K001-			Not		
31/10/2022 14:41	14:41		Failed - low	Incorrect	provided		
		BC008PTMS475119-			Not		
25/10/2022 08:04	08:04		Works stopped		provided		
		D2006-NETOM-		 	Not		
12/10/2022 12:28	12:28		Passed		provided		
					Ė		
05/10/2022 14:05	14:05	AD02660693112_TL2- INSP-01	Works stopped		Not provided		
, .			-		Ė		
06/09/2022 10:36	10.36	BC007WDHNN06W- INSP-01	Works stopped		Not provided		

		ı		ı			ı	
		AD037RO59746943_2_			Not			
31/08/2022 13:12	13:12	TL3-INSP-01	Works stopped		provided			
		BC311WD2PML6J002-			Not			
15/06/2022 15:05	15:05	INSP-01	Passed		provided			
45/02/20224442		JT60079742810-INSP-			Not			
16/02/2022 14:42	14:42	01	Works stopped	<u> </u>	provided	+		
		BC00828JANWD2V3L5			Not			
28/01/2022 15:33	15:33	H-INSP-01	Works stopped		provided			
					Not			
18/01/2022 15:54	15:54	EN013214104-INSP-03	Passed		provided			
1,1,1,1					l contraction			
		EN014M26602-INSP-			Not			
11/11/2021 11:30	11:30	02	Passed		provided			
		EN014M26602-INSP-			Not			
11/11/2021 11:30	11:30	01	Passed		provided			
		JT400HT0121-21-INSP-			Not			
28/10/2021 16:00	16:00		Works stopped		provided			
1, 1, 1					İ			
		EN014M40525-INSP-			Not			
25/10/2021 15:00	15:00	01	Works stopped		provided			
					Not			
27/07/2021 11:45	11:45	EN013214104-INSP-02	Passed		provided			
					Not			
27/07/2021 11:45	11:45	EN013214104-INSP-01	Passed		provided			
					p. 0.1.00			
		AZ0071000850526-	[Not			
30/06/2021 14:45	14:45	INSP-01	Passed		provided			

									Promoter		Highway	Highway
		Workst			Reason for				reason	Highway	authority	authority
	Inspector	ream		Inspection	withdrawa		Promoter	Promoter response	for	authority	response	reason for
Additional comments	name	prefix	Town	status	I	Withdrawal details	response	date	dispute	response	date	accepting
				L								
Two qay lights in situ on a refused permit		152	LINFORD	Recorded								
D/3 pass upon completion of remedial works		152	LINFORD	Recorded								
							1					
Completed and site clear		152	LINFORD	Recorded								
		152	LINFORD	Recorded								
		132	LINI OND	necorueu			1		1	 	 	
		152	LINFORD	Recorded								
Base on West Continue Colores		450	LINIEODD	D								
Pass on West Section of closure		152	LINFORD	Recorded								
S/A pass on West Section of works , junction with Blue Anchor												
Lane.		152	LINFORD	Recorded								
D/3 follow up completion fail 3 x locations of teack work that												
the 150mm proximty edge requirements have still not been							Inspection					
met and remain in situ. 1 additional one created as a result of							outcome					
the works *		152	LINFORD	Recorded			accepted	19/05/2023 12:59				
Routine B inspection passed		300	LINFORD	Recorded								
Som site clear		300	LINFORD	Recorded								
		330										
Som works cancelled		311	LINFORD	Recorded								
Pouting A increation passed		300	LINEODD	Docordod								
Routine A inspection passed		300	LINFORD	Recorded								
D/1 meeting held with ##### Telecoms. Dlareas marked up and												
agreed for remediation.		152	LINFORD	Recorded								

		1	г	_			 	
Consolte along	1.4	LINICODO	Dagandad					
Som site clear	14	LINFORD	Recorded					
Conditions passed	14	LINFORD	Recorded					
Conditions passed	1-7	LINIOND	Recorded					
Routine A inspection passed	14	LINFORD	Recorded					
		CHADWEL						
Som site clear	6	L ST MARY	Recorded					
L		CHADWEL	L					
Sample A inspection passed	6	L ST MARY	Recorded					
Som site clear	700	LINFORD	Pacardad					
Soft Site clear	700	LINFORD	Recorded					
Sample B inspection passed	14	LINFORD	Recorded					
The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon								
Som site clear	14	LINFORD	Recorded					
Som site clear	152	LINFORD	Recorded					
Routine A inspection low risk fail issues corrected by Jo barriers								
now been removed and men at work sign put wear missing	152	LINFORD	Recorded					
High risk SLG logged on site with team leader at 14:13pm								
####### WHP Telecoms.								
Trips on boards resolved- Rest of failures to be rectified.	152	LINFORD	Recorded					
L			L					
Sample A inspection passed	152	LINFORD	Recorded					

			т	ı	Ī			T	ı	
0/0.0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1										
S/B Reinstatement inspection fail. Please respond within 10										
working days and arrange for a remedial works permit to be										
submitted. Should the works assessment be challenged, please										
attend as required to an arranged D/1 joint site meeting on the										
06/04/23 at 11:00am Alternatively contact						Inspection				
########@thurrock.gov.uk or mobile ######## to arrange						outcome				
an alternative meeting date and time if required? Thank you.	152 LINFORD	Recorded				accepted	27/04/2023 10:18			
· · ·										
Pass inspection	14 LINFORD	Recorded								
Blue arrows missing from x1 lead tapering x1 at side of										
compound and cones										
Routine A low risk fail corrected by inspector from signs in										
compound	152 LINFORD	Recorded								
compound	132 LINI OND	Recorded								
	CHADWE	L								
Routine B inspection passed	14 L ST MAR									
Housing B inspection passed	14 231 101/41	1 Necoraea								
	CHADWE	1								
Som site clear	14 L ST MAR									
Som site tical	14 231 101/41	1 Necoraea								
	CHADWE	L								
Pass inspection. All lights functioning within normal parameters	14 L ST MAR									
r dos mopeocioni i in ignio ranocio ini g incimi no ini ai parameterio	2.1.201.11.11									
	CHADWE	L								
Lower risk SLG fail logged on site with ######## Totq TM.	14 L ST MAR									
20Wel 10K020 tell 108800 of the Well Imminimum Ford 11M	21,201,111,11									
Som site clear	7 LINFORD	Recorded								
	CHADWE	L								
Routine A inspection passed	14 L ST MAR	Y Recorded								
· ·										
Sam sita alaar	500 11015055	Doggrafaal								
Som site clear	600 LINFORD	Recorded								
Routine A inspection passed but site being taken down when										
photos were taken	152 LINFORD	Recorded								
Som site clear	152 LINFORD	Recorded								

					1			
Constitution of the second	_	LINIEODD	D d d					
Som site clear	/	LINFORD	Recorded					
	_							
Som site clear	7	LINFORD	Recorded					
Sample A inspection passed	152	LINFORD	Recorded					
Constitution		CLIADIA/EL						
Som site clear		CHADWEL						
Works still in progress	152	L ST MARY	Recorded					
		0114 014/51						
		CHADWEL						
Som site clear	411	L ST MARY	Recorded					
		CHADWEL						
Som site clear	152	L ST MARY	Recorded					
					reinstated on another phase of			
D/1 site meeting to discuss reinstatement failure attended by					works and the carriageway			
HA Inspector at time and date communicated. No					surface involved on the			
acknowledgement of defect, no contact made to accept and no					inspection has now been			
	211	LINFORD	Withdrawn	Other				
remedial permit submitted. Escalation required to resolve	311	LINFORD	withdrawn	Other	resurfaced removing the initial			
Reinstatement inspection fail. Interim status has expired.Please					These works were permanently			
respond within 10 working days and arrange for a remedial					reinstated on another phase of			
works permit to be submitted. Should the works assessment be					works and the carriageway			
challenged, please attend as required to an arranged D/1 joint					surface involved on the			
site meeting on the 22/11/22 at 11:00pm Alternatively contact					inspection has now been			
######@thurrock.gov.uk or mobile ###### to arrange an					resurfaced removing the initial			
alternative meeting date and time if required? Thank you	311	LINFORD	Withdrawn	Other	issue reported. *			
ancernative meeting date and time in required: mank you	511	2	****Cilaravvii	Other	issue reported.			
Som site clear								
Visual inspection carried out as no where to park	8	LINFORD	Recorded					
Tissa. Hispositori curricu duc as no where to park			ccoraca					
Sample A inspection passed		CHADWEL						
Advice given on site regarding spoil	6	L ST MARY	Recorded					
6 cit on site regarding spoil		201 141/41(1						
		CHADWEL						
Som site clear	26	L ST MARY	Recorded					
John Site Gear	20	E 21 IVIAINI	necoraea					
Som site clear	7	LINFORD	Recorded					
JOHI SILE CIECI	/	LIMI OND	necoraea					

			1	1		1			
		CHADWEL							
Som site clear		L ST MARY	Recorded						
Reinstatement has not been registered therefore no defects.									
Resident was concerned with the colour of the reinstatement									
when first completed but now is happy with the colour once it									
has dried.	311	LINFORD	Recorded						
nos aried.	311	LITTI OND	necoraea						
Site completed and cleared	600	LINFORD	Recorded						
Site clear	0	LINEODD	Dogardad						
Site clear	8	LINFORD	Recorded						
	13	LINFORD	Recorded						
						ĺ			
	14	LINFORD	Recorded						
	1.4	LINFORD	Danaudad						
	14	LINFORD	Recorded			+			
		CHADWEL							
		L ST MARY	Recorded						
						j			
	14	LINFORD	Recorded						
Pictures attached to routine inspection	13	LINFORD	Pocordod						
rictures attached to routine inspection	13	LINFUKD	necoraea			-			
	13	LINFORD	Recorded						
						İ			
	0	LINFORD	Recorded						