Section 81						Other			Inspect	Inspect			Promoter			
reference	Section 81	Location	Location	Inspection	Section 81	type	Section 81	Made safe	or	or	Section 81	Promoter	response	Promoter status		Section 81
number	status	types	description	date	type	details	severity	by HA	name	contact	additional details	response	details	changed date	Status changed date	work type
JTS8192639	Accepted		Linford Road jw Waterson Road,		Tee/valve						Treble lid manhole been driven over which has subsequently damaged the frame and dislodged the		complete			Permit
	•		Chadwell	15/06/2022	ľ		Low	No			surround.		WD0HWJ4G	23/12/2022 11:37	23/12/2022 11:37	
577 501	(incu)		Located between property named Mayland and the junction with	10,00,2022	Tee/valve		2011				surround.		Estimate WCCV412R Closed	25/22/2022 11:57	29, 22, 2022 22:07	wond
JTS8152333	Accepted	Carriagew	Standford		/access							Accepted	Complete26/0			Permit
664-S81	(fixed)	ay	Road.	24/08/2020	covers		Low	No				(fixed)	5/21	27/02/2022 18:36	27/02/2022 18:36	works

	Works					Section 81		Follow	Follow up	Follow			Workst			
Section 81 date	reference		Road/Stree		Road	coordinate	Works	up	inspection	up		Highway	ream		Linked	Photo
created	number	USRN	t	Area	category	S	status	inspectio	date	inspecti	Promoter	authority	prefix	Town	permit	evidence?
						Daint										
						Point:	Continu							CHADWE		
	JTS8192639		LINFORD			564745.33 ,178490.1						THURROCK		LL ST		
16/06/2022 17:3		40500802			1			Yes	13/07/2022		ВТ	COUNCIL		MARY		Yes
10/00/2022 17.3	1 377	40300802	ROAD		1	2	WUIKS	163	13/07/2022		וט	COONCIL	"	IVIANT		163
			DUICKINICU			Point:	C 1.'									
	ITC0452222		BUCKINGH			567157.73						THURBOCK	1			
25 /00 /2020 11-0	JTS8152333		AM HILL			,181667.4		.			D.T.	THURROCK		LINICORD		 N =
25/08/2020 11:0	+ 004	40500206	KUAD		1	3	works	No			BT	COUNCIL	<u> </u>	LINFORD		No