

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 002902

Address LINFORD ROAD CHADWELL ST MARY

Date Due 21/09/2021

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 21/09/2021 (Blank = Now) Mark Activity as Complete?

Inspector TH000021 3P

Next Due Date 21/11/2021 (Blank = Calculated) Next Done Date 18/11/2021

Weather Sunny Surface Type Dry

CW Condition Fair - Aes Poor FW Condition

Description driven safety inspection 3P no recordable defects. cw fair aesthetically poor

Last updated by TH000021 at 13:22 on 21/09/2021 Handheld

Thurrock 1/08/23

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 002974

Address LINFORD ROAD CHADWELL ST MARY

Date Due 21/11/2021

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 18/11/2021 13:18 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 18/01/2022 (Blank = Calculated) Next Done Date 19/01/2022

Weather Sunny Surface Type Dry

CW Condition Fair - Aes Poor FW Condition

Description Inspected 3P No recordable defects noted. Carriageway condition fair aesthetically poor

Last updated by TH000020 at 13:30 on 18/11/2021 Handheld

Thurrock 1/08/23

Page 1 of 1 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003230

Address LINFORD ROAD CHADWELL ST MARY

Date Due 17/05/2022

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 19/05/2022 13:44 (Blank = Now) Mark Activity as Complete?

Inspector TH000104 3P

Next Due Date 19/07/2022 (Blank = Calculated) Next Done Date 19/07/2022

Weather Rain Surface Type Wet

CW Condition Fair - Aes Poor FW Condition

Description Inspected by BP c/way in fair aesthetically poor condition. no recordable defects noted

Last updated by TH000104 at 14:54 on 19/05/2022 Prev Version Next Version Hand-held

Thurrock 1/08/23

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003300

Address LINFORD ROAD CHADWELL ST MARY

Date Due 19/07/2022

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 19/07/2022 13:47 (Blank = Now) Mark Activity as Complete?

Inspector TH000104 3P

Next Due Date 19/09/2022 (Blank = Calculated) Next Done Date 22/09/2022

Weather Sunny Surface Type Dry

CW Condition Fair - Aes Poor FW Condition

Description Inspected by BP c/way in fair aesthetically poor condition.

Last updated by TH000104 at 14:14 on 19/07/2022 Prev Version Next Version Hand-held

Thurrock 1/08/23

Page 3 of 3 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

AutoSave: ON Document1 - Word Search (Alt+Q) Scott, James

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations LA Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003370

Address LINFORD ROAD CHADWELL ST MARY

Date Due 19/09/2022

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 22/09/2022 14:34 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 22/11/2022 (Blank = Calculated) Next Done Date 17/11/2022

Weather Sunny Surface Type Dry

CW Condition Fair - Aes Poor FW Condition

Description Inspected 3P 3P No recordable defects noted. Carriageway condition poor

Last updated by TH000020 at 14:34 on 22/09/2022 Prev Version Next Version Handheld

Thurrock 1/08/23

Page 4 of 4 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

AutoSave: OFF Document1 - Word Search (Alt+Q) Scott, James

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations LA Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003454

Address LINFORD ROAD CHADWELL ST MARY

Date Due 22/11/2022

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 17/11/2022 13:29 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 17/01/2023 (Blank = Calculated) Next Done Date 18/01/2023

Weather Rain Surface Type Wet

CW Condition Poor FW Condition

Description Inspected 3P 3P No recordable defects noted. Carriageway condition poor

Last updated by TH000020 at 13:29 on 17/11/2022 Prev Version Next Version Handheld

Thurrock 1/08/23

Page 4 of 4 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

AutoSave **ON** Document1 - Word Search (Alt+Q) Scott, James

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003535

Address LINFORD ROAD CHADWELL ST MARY

Date Due 17/01/2023

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 18/01/2023 14:29 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 18/03/2023 (Blank = Calculated) Next Done Date 14/03/2023

Weather Overcast Surface Type Damp

CW Condition Poor FW Condition

Description Inspected 3P Carriageway condition poor

Last updated by TH000020 at 14:31 on 18/01/2023 Prev Version Next Version Hand-held

Thurrock 1/08/23

Page 5 of 5 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

Page 5 of 5 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

Type here to search 17:40 01/08/2023

AutoSave **ON** Document1 - Word Search (Alt+Q) Scott, James

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003598

Address LINFORD ROAD CHADWELL ST MARY

Date Due 18/03/2023

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 14/03/2023 14:57 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 14/05/2023 (Blank = Calculated) Next Done Date 16/05/2023

Weather Rain Surface Type Wet

CW Condition Poor FW Condition

Description Inspected 3P Carriageway condition poor

Last updated by TH000020 at 15:00 on 14/03/2023 Prev Version Next Version Hand-held

Thurrock 1/08/23

Page 5 of 5 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

Type here to search 17:41 01/08/2023

AutoSave ON Document1 - Word Search (Alt+Q) Scott, James (Scott@thurrock.gov.uk) is signed in

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003672

Address LINFORD ROAD CHADWELL ST MARY

Date Due 14/05/2023

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 16/05/2023 13:18 (Blank = Now) Mark Activity as Complete?

Inspector TH000104 3P

Next Due Date 16/07/2023 (Blank = Calculated) Next Done Date 19/07/2023

Weather Sunny Surface Type Dry

CW Condition Poor FW Condition

Description Inspected by 3P c/way lin poor condition. no recordable defects noted

Last updated by TH000104 at 14:08 on 16/05/2023 Prev Version Next Version Handheld

Thurrock 1/08/23

Page 6 of 6 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

AutoSave OFF Document1 - Word Search (Alt+Q) Scott, James (Scott@thurrock.gov.uk) is signed in

File Home Insert Design Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 003723

Address LINFORD ROAD CHADWELL ST MARY

Date Due 16/07/2023

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 19/07/2023 13:09 (Blank = Now) Mark Activity as Complete?

Inspector TH000104 3P

Next Due Date 19/09/2023 (Blank = Calculated)

Weather Rain Surface Type Wet

CW Condition Poor FW Condition

Description Inspected by 3P c/way in poor condition. no recordable defects noted

Last updated by TH000104 at 13:48 on 19/07/2023 Prev Version Next Version Handheld

Thurrock 1/08/23

Page 6 of 6 0 words English (United Kingdom) Accessibility: Investigate Focus 120%

17:41 01/08/2023

AutoSave ON Document1 - Word Search (Alt+Q) Scott, James

File Home Insert Design

Layout References Mailings Review View Help

Insight Enterprise - Cyclic Activities - Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations LA Codes Observation Objects Activity Objects

Activity Type SID Safety Inspection Driven Survey 002839

Address LINFORD ROAD CHADWELL ST MARY

Date Due 20/07/2021

Frequency 2 Months Standard Frequency 2 Months

Done Date/Time 21/07/2021 13:29 (Blank = Now) Mark Activity as Complete?

Inspector TH000020 3P

Next Due Date 21/09/2021 (Blank = Calculated) Next Done Date 21/09/2021

Weather Sunny Surface Type Dty

CW Condition Fair - Aes Poor FW Condition

Description Inspected 3P No recordable defects noted. Carriageway condition fair aesthetically poor

Last updated by TH000020 at 13:30 on 21/07/2021 Prev Version Next Version Handheld

Thurrock 1/08/23

Page 1 of 1 0 words English (United Kingdom) Accessibility: Good to go Focus 120%

Type here to search 17:37 01/08/2023