Location	Inspection Type	Done Date/Time	Date Due	Region/Site	Inspection Completed?	Description	L.A.Codes?	LA Defect	LA Defect Desc	Status	Inspection Weather	Highway Surface	CW Condition	FW Condition
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	05/03/2024 12:01	03/03/2024	405/00052		No recordable defects noted. Large area of carriageway been resurfaced.	N				Rain	Wet	Fair - Aes Poor	
ARISDALE AVENUE, SOUTH OCKENDON	Annual Walked	08/01/2024 13:50	12/12/2023	405/00052	Υ	f\way in poor condition. vehicles parked on f\way. extensive f\way reconstruction both sides between Avontar and West Rd by H&T	N				Snow	Wet	Poor	Poor
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	03/01/2024	02/01/2024	405/00052	Υ	cw poor	Υ	37603	20x potholes between West Rd and Avontar Rd	Repaired	Sunny	Dry	Poor	
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	02/11/2023	06/11/2023	405/00052	Υ	c\way in poor condition	Υ	36910	potholes and centre line spalling equal to 20x potholes between West Rd and Avontar Rd	Repaired	Rain	Wet	Poor	
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	06/09/2023 14:09	04/09/2023	405/00052	Υ	No rush recordable defects noted. Carriageway condition poor	N				Sunny	Dry	Poor	
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	04/07/2023 13:27	04/07/2023	405/00052	Υ	c\way in poor condition.	Υ	35835	1x pothole j/o Avontar, & 6x potholes j/o Winstar	Repaired	Overcast	Dry	Poor	
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	04/05/2023 13:40	01/05/2023	405/00052	Υ	Carriageway condition poor	Υ	35271	1x pothole o/s 246	Repaired	Overcast	Dry	Poor	
ARISDALE AVENUE, SOUTH OCKENDON	2 Monthly Driven	01/03/2023 13:01	04/03/2023	405/00052	Y	No recordable defects noted. Carriageway condition poor.	N				Rain	Wet	Poor	
									. 0					
						4			YK					
							A							
						Ca								
						~ ~ ~ ~								
						70								